| UST Service Provider List (All) - Env | ironmental Service Firms Only |
|---------------------------------------|-------------------------------|
| | |

| Company | | Listing Submitted | 8/4/2020 | Area of state conducts work | |
|---|---|---|---|--|----------------------------|
| Advanced Environmental Services, Inc. | Pho | ne (336) 282-3586 | | Coastal (East of I-95): Yes | |
| PO Box 38218 | F | ax (336) 282-3587 | | Central (West of I-95 and East of I-77): Yes | |
| Greensboro, NC 27438 | | | | Mountains (West of I-77): Yes | |
| | Websi | ite <u>advancedenvironmental.com</u> | | | |
| Comp | oliance Testing a | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ove | erfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Stat | tistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spil | I Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tan | k Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No UST | T Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST | T Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Oth | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | rvice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes US | Γ Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | · · · · · · · · · · · · · · · · · · · | Γ Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | ste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Oth | | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 5/17/2021 | Area of state conducts work | |
| AES of Greenville LLC | Pho | one (252) 758-3311 | | Coastal (East of I-95): Yes | |
| 141 S. Market Street | F | ax (252) 481-5814 | | Central (West of I-95 and East of I-77): Yes | |
| Washington, NC 27889 | | . , | | Mountains (West of I-77): Yes | |
| | Websi | ite <u>www.aes-nc.com</u> | | , | |
| Comp | oliance Testing a | and Monitoring | | | |
| Automatic Line Leak Detector Testing: | | and Monitoring | | UST Equipmment Service Contractors | |
| | | erfill Prevention Equipment Operability Check: | Yes | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | Yes Ove | | <u>Yes</u> <u>Yes</u> | | No No |
| Containment Sump Testing: Corrosion Protection Design Experts: | Yes Ove | erfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Yes Over Yes Star No Spil | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: | <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | Yes Over Yes Stat No Spil Yes Tan | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: | <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Yes Over Yes Star No Spil Yes Tan Yes UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: | <u>Yes</u> <u>Yes</u> Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes Over Yes Star No Spil Yes Tan Yes UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | <u>Yes</u> <u>Yes</u> <u>Yes</u> Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes Over Yes Star No Spil Yes Tan Yes UST Yes UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | <u>Yes</u> <u>Yes</u> <u>Yes</u> Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Ove Yes Star No Spil Yes Tan Yes UST Yes UST Yes Oth | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: lk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: | <u>Yes</u> <u>Yes</u> <u>Yes</u> Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Yes Ove Yes Star No Spil Yes Tan Yes UST Yes Oth Yes Oth Yes | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: lk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: | <u>Yes</u> <u>Yes</u> <u>Yes</u> Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Ove Yes Star No Spil Yes Tan Yes UST Yes Oth Yes Oth Yes No UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: If Internal Inspections (Integrity Assessments): If Internal Lining Inspections: er: | Yes Yes Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Yes Ove Yes Star No Spil Yes Tan Yes UST Yes Oth Yes Oth Yes No UST No UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: tk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: Tryice Firms T Compliance Consultants: | Yes Yes Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Ove Yes Star No Spil Yes Tan Yes UST Yes Oth Yes Oth Yes No UST No UST | erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: Ervice Firms T Compliance Consultants: T Equipment Verification: ste Disposal and Treatment: | Yes Yes Yes Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitted | 4/15/2021 | Area of state conducts work | |
|---|-------------------|---|------------|--|------------|
| American UST Compliance Testing | Phoi | ne (919) 777-8543 | | Coastal (East of I-95): Yes | |
| 180 BPW Club Rd. A-1 | F: | ax | | Central (West of I-95 and East of I-77): Yes | |
| Carrboro, NC 27510 | | | | Mountains (West of I-77): Yes | |
| | Websi | te | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testing a | nd Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | Yes Over | rfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | Yes Stati | istical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spill | Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No Tank | k Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | Yes UST | Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Othe | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | No |
| Er | nvironmental Ser | vice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes UST | Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No UST | Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No Was | ste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No Othe | er: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 5/17/2021 | Area of state conducts work | |
| Apex Engineering, PC | Phoi | ne (301) 417-0200 | | Coastal (East of I-95): Yes | |
| 15850 Crabbs Branch Way | F | ax (301) 975-0169 | | Central (West of I-95 and East of I-77): Yes | |
| Suite 200 | | (201) 312 3133 | | Mountains (West of I-77): Yes | |
| Rockville, Maryland 20855- | Websit | te <u>www.apexcos.com</u> | | Wouldains (West of 1-77). Tes | |
| Comp | oliance Testing a | nd Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Over | rfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Stati | istical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spill | Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tank | k Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No UST | Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST | Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Othe | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Ser | vice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes UST | Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | | Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | ste Disposal and Treatment: | Yes | | |
| zirineimientai zirgineen eestegiet een ana err ereana | | · · · · · · · · · · · · · · · · · · · | | | |
| Oil and Solvent Recycling: | Yes Othe | | | | |

| UST Se | ervice Pro | vider List (All) - Environment | al Service | e Firms Only | |
|---|-----------------|--|------------|--|-----|
| Company | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
| Blue Ridge Geological Services, Inc. | PI | none (336) 382-6849 | | Coastal (East of I-95): Yes | ; |
| 7356 Belmont Drive | | Fax | | Central (West of I-95 and East of I-77): Yes | 6 |
| Trinity, NC 27370 | | | | Mountains (West of I-77): Yes | |
| | Web | site <u>www.blueridgegeo.com</u> | | moditalits (West of 1-11). Tes | • |
| Com | pliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | verfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | tatistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | pill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No U | ST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No U | ST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No C | ther: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | No |
| E | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> U | ST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> U | ST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | y <u>Yes</u> V | aste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No C | ther: | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| Company | | Listing Submitted | 2/1/2021 | Area of state conducts work | |
| Buckeye Elm Contracting | PI | none (888) 315-8663 | | Coastal (East of I-95): Yes | ; |
| PO Box 1026 | | Fax | | Central (West of I-95 and East of I-77): Yes | 6 |
| Mocksville, NC 27028 | | | | Mountains (West of I-77): Yes | |
| | Web | site <u>www.buckeye-elm.com</u> | | mountaine (Woot of 177). | |
| Com | pliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | verfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | tatistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | pill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No U | ST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No U | ST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| | NI- | ther: | | UST Piping/Sump Installation: | No |
| Leak Detection Monitoring Services: | No C | uici. | | OST Tiping/Sump installation. | INO |

Soil and Water Testing Lab:

Emergency Cleanup - Spill/Release:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu No

No

No

<u>Yes</u>

UST Compliance Consultants:

Waste Disposal and Treatment:

UST Equipment Verification:

Other:

<u>Yes</u>

<u>Yes</u>

No

| UST Se | ervice | Provider List (All) - Environment | al Servic | e Firms Only | |
|--|------------|---|------------|--|----|
| Company | | Listing Submitted | 1/10/2022 | Area of state conducts work | |
| Bunnell-Lammons Engineering, Inc. | | Phone (828) 277-0100 | | Coastal (East of I-95): Yes | 6 |
| 130 Oval Road | | Fax (828) 277-0110 | | Central (West of I-95 and East of I-77): Yes | 3 |
| Arden, NC 28704 | | (0=0) = 1 1 0 1 1 0 | | Mountains (West of I-77): Yes | |
| | | Website www.blecorp.com | | Mountains (West of 1-11). Tes | • |
| Comp | pliance | Testing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | <u>Yes</u> | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | <u>Yes</u> | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | <u>Yes</u> | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | No |
| Ei | nvironn | ental Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No | Other: Trust Fund | Projects | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 5/18/2022 | Area of state conducts work | |
| Cape Fear Engineering, Inc. | | Phone (910) 383-1044 | | Coastal (East of I-95): Yes | 3 |
| 151 Poole Road | | Fax | | Central (West of I-95 and East of I-77): No | |
| Suite 100 | | | | Mountains (West of I-77): No | |
| Leland, NC 28451 | | Website www.capefearengineering.com | | mountains (west of 177). To | |
| Comp | oliance | Testing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Ei | nvironm | nental Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| The state of the s | | | | | |

Soil and Water Testing Lab:

Environmental Engineer/Geologist - Site Checks:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

No

<u>Yes</u>

UST Equipment Verification:

Other:

Waste Disposal and Treatment:

<u>Yes</u>

No

| Company | | Listing Submitted | 5/18/2022 | Area of state conducts work | |
|---|---|--|------------|---|------------------|
| Cape Fear Engineering, Inc. | | Phone (910) 383-1044 | | Coastal (East of I-95): Yes | |
| 151 Poole Road | | Fax | | Central (West of I-95 and East of I-77): No | |
| Suite 100 | | | | Mountains (West of I-77): No | |
| Leland, NC 28451 | We | ebsite <u>www.capefearengineering.com</u> | | Mountains (West of 1-77): No | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmenta | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 4/5/2023 | Area of state conducts work | |
| CATLIN Engineers and Scientists | ļ | Phone (910) 452-5861 | | Coastal (East of I-95): Yes | |
| 220 Old Dairy Road | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28405 | | | | Mountains (West of I-77): No | |
| | We | ebsite www.CatlinUSA.com | | mountaino (troot or 177). Tro | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| | | | | LIOT Occident Installation Commission Constant | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: | | UST Internal Lining Inspections: Other: | No | UST Piping/Sump Installation: | No |
| | | | No | UST Piping/Sump Installation: UST System Removal: | No <u>Yes</u> |
| Leak Detection Monitoring Services: Line Tightness Testing: | No No | | No . | UST Piping/Sump Installation: | |
| Leak Detection Monitoring Services: Line Tightness Testing: | No No nvironmental | Other: | No Yes | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: | No No nvironmental Yes | Other: Service Firms | | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No No nvironmental Yes Yes | Other: Service Firms UST Compliance Consultants: | <u>Yes</u> | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No nvironmental Yes Yes Yes | Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | Yes No | UST Piping/Sump Installation: UST System Removal: | |

| UST Service Provider List (All) - Environmental | Service | Firms Only |
|---|----------|-------------|
| Listing Submitted | 4/5/2023 | Area of sta |

| Company | | Listing Submitted | d 4/5/2023 | Area of state conducts work | |
|---|--|--|--------------------------------------|--|---------------------------------|
| CDG, Inc. | | Phone (704) 394-6913 | | Coastal (East of I-95): Yes | |
| 4301 Taggart Creek Road | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Charlotte, NC 28208 | | | | Mountains (West of I-77): Yes | |
| | W | ebsite <u>www.cdge.com</u> | | mountains (West Of 177). 103 | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | <u>Yes</u> | Other: | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| Commons | | | | | |
| Company | | Listing Submitted | d 8/18/2020 | Area of state conducts work | |
| Charles Broadfoot & Associates, Inc. | | Phone (910) 574-4748 | d 8/18/2020 | Coastal (East of I-95): Yes | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 | | | d 8/18/2020 | | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. | | Phone (910) 574-4748 Fax 253-681-05 | d 8/18/2020 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 | | Phone (910) 574-4748 | d 8/18/2020 | Coastal (East of I-95): Yes | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 | W | Phone (910) 574-4748 Fax 253-681-05 | d 8/18/2020 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 | W | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com | d 8/18/2020 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comp | Woliance Testi | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors | Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | Wo Dliance Testi Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Wooliance Testi Off Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Off Off Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Williance Testi Off Off Off Off Off Off Off Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Off Off Off Off Off Off Off Off Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Williance Testi Off Off Off Off Off Off Off Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | Off Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: | Off Off Off Off Off Off Yes | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Off | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: | Off Off Off Off Off Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off Off |
| Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu | Office Testion Office O | Phone (910) 574-4748 Fax 253-681-05 ebsite www.ustcomonline.com ng and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment: | Off Off Off Off Off Off Off Off Off | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Off Off Off Off Off |

| Company | | Listing Submitted | 5/26/2021 | Area of state conducts work | |
|---|---|--|------------------------|---|----------|
| Christopher Dunlap, P.G. | | Phone (828) 505-6301 | | Coastal (East of I-95): No | |
| 166 Michigan Avenue | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Asheville, NC 28806 | | T un | | Mountains (West of I-77): Yes | |
| | | Website | | Wouldains (West of 1-77). Tes | |
| Comp | oliance Te | sting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Ei | nvironmer | ntal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | d 6/17/2020 | Area of state conducts work | |
| Clark Group dba Clark Environmental Services | s. PC | Phone (910) 392-5555 | | Coastal (East of I-95): Yes | |
| P.O. Box 10136 | ٥, . ٠ | , , | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28404 | | Fax (910) 392-5552 | | | |
| | | Website www.clarkgroup.us | | Mountains (West of I-77): Yes | |
| Comp | oliance Te | sting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| | INO | rank rightness resting. | No | | NI- |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | | | | | No |
| | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | |
| Leak Detection Equipment Operability Check: | No No | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No | UST Equipment Repair: UST System Installation - Complete Systems: | No |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No | UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No nvironme r | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No | UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: | No No No No nvironmer Yes | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: htal Service Firms UST Compliance Consultants: | No No Yes | UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No nvironmer Yes Yes | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Other: UST Compliance Consultants: UST Equipment Verification: | No No Yes Yes | UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No |
| Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No nvironmer Yes Yes | UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: htal Service Firms UST Compliance Consultants: | No No Yes | UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No |

| UST Service Provider List (| All) | Environmental Sei | rvice Firms Only |
|------------------------------------|------|---------------------------------------|------------------|
|------------------------------------|------|---------------------------------------|------------------|

| Company | | Listing Submitted | 5/14/2021 | Area of state conducts work | |
|---|--|--|---|--|----------------------------|
| Cobb Environmental & Technical Services, Inc | . F | Phone (662) 841-0995 | | Coastal (East of I-95): Yes | |
| P. O. Box 1602, Tupelo, MS 38802 | | Fax (662) 841-0810 | | Central (West of I-95 and East of I-77): Yes | |
| 871 South Green Street | | (602) 611 6616 | | Mountains (West of I-77): Yes | |
| Tupelo, MS 38804 | We | ebsite <u>www.cobbenv.com</u> | | Modificants (West of 1-77). Tes | |
| Comp | liance Testir | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 1/20/2022 | Area of state conducts work | |
| | | | .,_0,_0 | | |
| COHESION, INC | F | Phone (919) 233-8626 | 1,20,2022 | Coastal (East of I-95): Yes | |
| 5216 YATES MILL POND RD | F | | ., | Coastal (East of I-95): Yes | |
| · · | F | Phone (919) 233-8626 Fax | ., | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| 5216 YATES MILL POND RD | | Phone (919) 233-8626 | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | Coastal (East of I-95): Yes | |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 | We | Phone (919) 233-8626 Fax | 77207202 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 | We | Phone (919) 233-8626 Fax Phone (919) 233-8626 WWW.COHESION-INC.COM | No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No | No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 | We bliance Testin No | Phone (919) 233-8626 Fax Spoke WWW.COHESION-INC.COM Ing and Monitoring | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors | No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | We bliance Testin No No | Phone (919) 233-8626 Fax Spite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: | No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | We pliance Testin No No No No | Phone (919) 233-8626 Fax Posite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Webliance Testin No No No No No | Phone (919) 233-8626 Fax Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Webliance Testin No No No No No No | Phone (919) 233-8626 Fax Sebsite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: | Webliance Testine No | Phone (919) 233-8626 Fax Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Webliance Testin No No No No No No | Phone (919) 233-8626 Fax Sebsite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Webliance Testine No | Phone (919) 233-8626 Fax Sebsite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Webliance Testin | Phone (919) 233-8626 Fax Posite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er | Webliance Testine No | Phone (919) 233-8626 Fax Posite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| 5216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Webliance Testine No | Phone (919) 233-8626 Fax Posite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| S216 YATES MILL POND RD RALEIGH, NC 27606 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Webliance Testin | Phone (919) 233-8626 Fax Posite WWW.COHESION-INC.COM Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Subm | nitted 12/30/2021 | Area of state conducts work | |
|--|--------------------------------|---|-------------------|--|------------|
| Crompco, LLC | | Phone (610) 278-7203 | | Coastal (East of I-95): Yes | |
| 1815 Gallagher Road | | Fax (610) 278-7621 | | Central (West of I-95 and East of I-77): Yes | |
| Plymouth Meeting, PA 19462 | | (010) 270 7021 | | Mountains (West of I-77): Yes | |
| | W | ebsite <u>www.crompco.com</u> | | wountains (west of 1-77). Tes | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | Yes Yes | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments) |): No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | No |
| Er | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Subm | nitted 9/28/2022 | Area of state conducts work | |
| D. H. Griffin Wrecking Company | | Phone (336) 214-9012 | | Coastal (East of I-95): Yes | |
| 4716 Hilltop Road | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Greensboro, NC 27407 | | | | Mountains (West of I-77): Yes | |
| | W | ebsite <u>www.dhgriffin.com</u> | | wountains (west of 1-77). Tes | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | . No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments) |): No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| _ | | | | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: | No | | | | |
| | No | I Service Firms | | Other: | |
| | No | I Service Firms UST Compliance Consultants: | No | Other: | |
| Er | No nvironmenta | | No No | Other: | |
| Emergency Cleanup - Spill/Release: | No nvironmenta Yes No | UST Compliance Consultants: | | Other: | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No nvironmenta Yes No | UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment: | No | Other: | |

| Company | | Listing Submitted | 5/26/2020 | Area of state conducts work | |
|---|--|---|------------------------------------|--|--------------------------|
| East Coast Environmental PA | | Phone (919) 772-0268 | | Coastal (East of I-95): Yes | |
| 3815 Junction Boulevard | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27603 | | | | Mountains (West of I-77): No | |
| | V | Website eastcoastenv.com | | mountains (west of 177). No | |
| Comp | oliance Tes | ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironment | al Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 4/5/2023 | Area of state conducts work | |
| East Coast Environmental, PA | | Phone (919) 349-5969 | | Coastal (East of I-95): Yes | |
| 3815 Junction Boulevard | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27603 | | | | Mountains (West of I-77): No | |
| | V | | | | |
| Comr | • | Website eastcoastenv.com | | Woultains (West of 1-77). No | |
| | | Website eastcoastenv.com ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | | No | · · · | No |
| - | oliance Tes | ting and Monitoring | No No | UST Equipmment Service Contractors | No <u>Yes</u> |
| Automatic Line Leak Detector Testing: | oliance Tes | ting and Monitoring Overfill Prevention Equipment Operability Check: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | <u>Yes</u> <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes Yes Yes No Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes No Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes No Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | No N | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes No Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No No No No Ves Yes | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes No Yes |

| Company | | Listing Submitted | 4/6/2023 | Area of state conducts work | |
|--|---|--|----------------------------|--|----------------------------|
| East Coast Environmental, PA | | Phone (919) 349-5969 | | Coastal (East of I-95): Yes | |
| 3815 Junction Boulevard | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27603 | | | | Mountains (West of I-77): No | |
| | V | Vebsite <u>eastcoastenv.com</u> | | mountains (West of 177). No | |
| Comp | pliance Tes | ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Ei | nvironment | al Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 2/1/2021 | Area of state conducts work | |
| EHC Environmental | | Phone (910) 843-4456 | | Coastal (East of I-95): Yes | |
| 207 West Fourth Avenue | | Fax (910) 843-5376 | | Central (West of I-95 and East of I-77): Yes | |
| Red Springs, NC 28377 | | | | Mountains (West of I-77): No | |
| | V | Vebsite | | , , | |
| Comp | pliance Tes | ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | | | | No |
| Containment Sump Testing: | INO | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | INO |
| | No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | | | | |
| | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: | No No No No No No No No Vo rvironment Yes No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No No No Vo rvironment Yes No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No No No No No No Ves | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
|--|--|--|--|--|-----------------------------|
| Environmental Contracting & Consulting Serv | ices, P | Phone (757) 912-2276 | | Coastal (East of I-95): Yes | |
| 10 3rd Avenue | | Fax | | Central (West of I-95 and East of I-77): No | |
| Southern Shores, NC 27949 | | | | Mountains (West of I-77): No | |
| | | Website | | mountains (west of 177). No | |
| Comp | oliance Te | esting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Ei | nvironme | ntal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | Yes | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Waste Disposal and Treatment: | Yes | | |
| Oil and Solvent Recycling: | Yes | Other: tank removals and in-situ | closures | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| Company | | Listing Submitted | 8/4/2020 | Area of state conducts work | |
| Environmental Laboratories, Inc | | Phone (864) 370-0637 | | Coastal (East of I-95): Yes | |
| PO Box 1729 | | Fax (864) 752-0948 | | Central (West of I-95 and East of I-77): Yes | |
| Travelers Rest, SC 29609 | | Fax (604) 752-0946 | | | |
| | | Website www.elabsinc.net | | Mountains (West of I-77): Yes | |
| ^ | | www.elabsinc.net | | | |
| Com | oliance Te | esting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | oliance Te | | Yes | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| | , | esting and Monitoring | <u>Yes</u> No | | Yes Yes |
| Automatic Line Leak Detector Testing: | Yes | esting and Monitoring Overfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | Yes Yes No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | <u>Yes</u> <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Yes Yes No Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes Yes No Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes Yes No Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No Yes Yes Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No Yes Yes Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No Yes Yes Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No Yes Yes Yes Yes Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | Yes Yes No Yes Yes Yes Yes Yes Yes Yes No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: | No Yes Yes Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Yes No Yes Yes Yes Yes Yes Yes Yes No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: UST Equipment Verification: | No Yes Yes Yes Yes Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |

| Company | | Listing Submitted | 1/4/2022 | Area of state conducts work | |
|--|--|---|----------------------------|--|----------------------------|
| EnviroTrac Ltd. | | Phone (336) 763-6025 | | Coastal (East of I-95): Yes | |
| 7343 West Friendly Avenue | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Suite J | | | | Mountains (West of I-77): Yes | |
| Greensboro, NC 27410 | W | ebsite envirotrac.com | | would all s (West of 1-77). Tes | |
| Comp | oliance Test | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Ei | nvironmenta | al Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| Company | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
| Envirovation Geologic Consulting and Mappin | ıg, PC | Phone (828) 407-0613 | | Coastal (East of I-95): No | |
| 719-A Greenway Rd | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| PO Box 3425 Boone, NC 28607 | | | | * | |
| Boone NL. 28607 | | | | Mountains (West of L-77): Yes | |
| 20010, 110 20001 | W | /ebsite https://envirovationconsulting.com/ | | Mountains (West of I-77): Yes | |
| | | | | Mountains (West of I-77): Yes UST Equipmment Service Contractors | |
| | | /ebsite https://envirovationconsulting.com/ | No | | No |
| Comp | oliance Test | /ebsite https://envirovationconsulting.com/ ing and Monitoring | No No | UST Equipmment Service Contractors | No No |
| Comp Automatic Line Leak Detector Testing: | oliance Test No | /ebsite https://envirovationconsulting.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | /ebsite https://envirovationconsulting.com/ ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No No No No | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No No | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No No No | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | No N | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: In Service Firms UST Compliance Consultants: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | | Listing Submitted | 1/3/2022 | Area of state conducts work | |
|---|--|--|---|----------------------------------|--|----------------------------------|
| Evo Corporation | | Phone (33 | 36) 725-5844 | | Coastal (East of I-95): Yes | |
| 1703 Vargrave Street | | Fax | , | | Central (West of I-95 and East of I-77): Yes | |
| Winston-Salem, NC 27107 | | Tux | | | | |
| | W | ebsite <u>ww</u> | <u>w.evocorp.net</u> | | Mountains (West of I-77): Yes | |
| Comp | oliance Testi | ing and Mor | nitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Preve | ention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Ive | entory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevent | ion Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightne | ess Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal | Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal | Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmenta | I Service Fi | rms | | Other: Vacuum Truck | Services |
| Emergency Cleanup - Spill/Release: | Yes | UST Complia | ance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipm | ent Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | | osal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | <u>Yes</u> | Other: | Transportation S | | | |
| Soil and Water Testing Lab: | No | | · | | | |
| | | | | | | |
| Company | | | Listing Submitted | 7/29/2020 | Area of state conducts work | |
| Company Event Environmental Associates BLLC | | Phone (70 | Listing Submitted | 7/29/2020 | Area of state conducts work | |
| Excel Environmental Associates, PLLC | | • | 04) 853-0800 | 7/29/2020 | Coastal (East of I-95): Yes | |
| Excel Environmental Associates, PLLC 625 Huntsman Court | | • | | 7/29/2020 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| Excel Environmental Associates, PLLC | | Fax (70 | 04) 853-0800 | 7/29/2020 | Coastal (East of I-95): Yes | |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 | w | Fax (70 | 04) 853-0800 04) 853-3949 w.excelengr.com | 7/29/2020 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp | W oliance Testi | Fax (70 ebsite www | 04) 853-0800 04) 853-3949 w.excelengr.com | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors | |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: | W Dliance Testi No | Fax (70 ebsite www ing and Mor Overfill Prevent | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: | No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | W Dliance Testi No No | Fax (70 ebsite www ing and Mor Overfill Preve Statistical Ive | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: | No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | W Dliance Testi No No No | Fax (70 ebsite www ing and Mor Overfill Prevent Statistical Ive Spill Prevent | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: ion Equipment Testing: | No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | W Dliance Testi No No No No | Fax (70 ebsite www ing and Mor Overfill Preve Statistical Ive Spill Prevent Tank Tightne | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: | No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Wollance Testi No No No No No | Fax (70 ebsite www. ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: Inspections (Integrity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | W Dliance Testi No No No No | Fax (70 ebsite www. ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: | No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: | Woliance Testi No No No No No No | Fax (70 ebsite www. ing and Mor Overfill Preve Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: Inspections (Integrity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Fax (70 ebsite www. ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal Other: | 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: ion Equipment Testing: ess Testing: Inspections (Integrity Assessments): Lining Inspections: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Fax (70 ebsite www. ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal UST Internal Other: | 04) 853-0800 04) 853-3949 ww.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: Inspections (Integrity Assessments): Lining Inspections: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No N | Fax (70 ebsite www ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal Other: Il Service Fi UST Complia | 04) 853-0800 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: ion Equipment Testing: ess Testing: Inspections (Integrity Assessments): I Lining Inspections: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Fax (70 ebsite www ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal Other: Il Service Fi UST Complia UST Equipm | nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: I Inspections (Integrity Assessments): I Lining Inspections: rms ence Consultants: enert Verification: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu | No N | Fax (70 Tebsite www. Ting and Mor Overfill Prevent Tank Tightne UST Internal UST Internal Other: UST Complia UST Equipm Waste Dispo | 04) 853-0800 04) 853-0800 04) 853-3949 w.excelengr.com nitoring ention Equipment Operability Check: entory Reconciliation Services: ion Equipment Testing: ess Testing: Inspections (Integrity Assessments): I Lining Inspections: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Fax (70 ebsite www ing and Mor Overfill Prevent Statistical Ive Spill Prevent Tank Tightne UST Internal UST Internal Other: Il Service Fi UST Complia UST Equipm | nitoring ention Equipment Operability Check: entory Reconciliation Services: cion Equipment Testing: ess Testing: I Inspections (Integrity Assessments): I Lining Inspections: rms ence Consultants: enert Verification: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |

| UST Service Provider List (All) - Environmental Service Firms Only | |
|--|--|
|--|--|

| Company | | Li | isting Submitted | 1/1/2022 | Area of state conducts work | |
|---|--|---|------------------|----------------------------|--|----------------------------|
| Galloway | | Phone (303) 770-8884 | | | Coastal (East of I-95): Yes | |
| 6162 South Willow Drive | | Fax (303) 770-3636 | | | Central (West of I-95 and East of I-77): Yes | |
| Suite 320 | | (600) 770 0000 | | | Mountains (West of I-77): Yes | |
| Greenwood Village, CO 80111 | W | ebsite <u>www.Gallowayus.com</u> | | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testi | ng and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Oper | rability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation S | ervices: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | <u>Yes</u> | Spill Prevention Equipment Testing | : | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity | Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | UST/AST System I | Design | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | No |
| Er | nvironmenta | I Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | | No | | |
| Oil and Solvent Recycling: | No | Other: | UST/AST System [| Design | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | Li | isting Submitted | 12/30/2021 | Area of state conducts work | |
| Geo-Hydro Engineers, Inc. | | Phone (704) 837-7174 | | | Coastal (East of I-95): Yes | |
| 2748 Interstate Street | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Suite A | | | | | , | |
| Charlotte, NC 28208 | | | | | Mountains (West of L-77): Yes | |
| , | W | ebsite www.geohydro.com | | | Mountains (West of I-77): Yes | |
| · | | ebsite www.geohydro.com ng and Monitoring | | | Mountains (West of I-77): Yes UST Equipmment Service Contractors | |
| · | | | rability Check: | No | · · · | No |
| Сотр | oliance Testi | ng and Monitoring | | No No | UST Equipmment Service Contractors | No No |
| Comp Automatic Line Leak Detector Testing: | oliance Testi No | ng and Monitoring Overfill Prevention Equipment Oper | ervices: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | ng and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S | ervices: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity) | services: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No | ng and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: | services: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No No No | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity) | services: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No No No | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: | services: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity A UST Internal Lining Inspections: | services: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | ng and Monitoring Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity / UST Internal Lining Inspections: Other: | services: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity JUST Internal Lining Inspections: Other: | services: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No N | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: | services: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Overfill Prevention Equipment Oper Statistical Iventory Reconciliation S Spill Prevention Equipment Testing Tank Tightness Testing: UST Internal Inspections (Integrity of UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: | services: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitted | | Area of state conducts work | |
|---|--|--|----------------------------|---|----------------------|
| Geological Resources, Inc. | F | Phone (704) 845-4010 | | Coastal (East of I-95): Yes | |
| 3502 Hayes Road | | Fax (704) 845-4012 | | Central (West of I-95 and East of I-77): Yes | |
| Monroe, NC 28112 | | 1 dx (704) 045-4012 | | | |
| | We | bsite grienv.com | | Mountains (West of I-77): Yes | |
| Comp | oliance Testir | g and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 11/18/2020 | Area of state conducts work | |
| Groundwater Management Associates, Inc. | F | Phone (252) 758-3310 | | Coastal (East of I-95): Yes | |
| 4300 Sapphire Court | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Suite 100 | | | | Mountains (West of I-77): Yes | |
| Greenville, NC 27834 | We | bsite www.gma-nc.com | | mountains (west of 1-77). Tes | |
| Comp | oliance Testin | g and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | | 110 | | |
| | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No | Spill Prevention Equipment Testing: Tank Tightness Testing: | No | | |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No | Spill Prevention Equipment Testing: | No No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No | Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Signal No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No nvironmental | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No No No No No No No No nvironmental No Yes | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No No nvironmental No Yes Yes | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |

| UST Se | rvice | Provider List (All) - Environment | ai Seivici | | |
|---|--|---|----------------------------|--|----------------------------------|
| Company | | Listing Submitted | 4/20/2023 | Area of state conducts work | |
| GTA Associates, In.c | | Phone (704) 553-2300 | | Coastal (East of I-95): No | |
| 701 Peninsula Lane, Suite B | | Fax (704) 553-2400 | | Central (West of I-95 and East of I-77): Yes | 6 |
| Charlotte, NC 28226 | | MATERIAL STATE | | Mountains (West of I-77): No | |
| | | Website www.gtaeng.com | | , , | |
| Comp | oliance Te | esting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmer | ntal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
| Highlands Environmental Solutions, Inc. | | Phone (919) 848-3155 | | Coastal (East of I-95): Yes | 3 |
| 8410-d Falls of Neuse | | Fax | | Central (West of I-95 and East of I-77): Yes | 6 |
| Raleigh, NC 27615 | | | | | |
| 1.000 | | | | Mountains (West of I-77): Yes | 3 |
| 1. Calongri, 110 27010 | | Website www.HESfast.com | | Mountains (West of I-77): Yes | 3 |
| - | | Website www.HESfast.com esting and Monitoring | | Mountains (West of I-77): Yes UST Equipmment Service Contractors | S |
| - | | | No | · · · · | No |
| Сотр | oliance Te | esting and Monitoring | No No | UST Equipmment Service Contractors | |
| Comp Automatic Line Leak Detector Testing: | oliance Te No | esting and Monitoring Overfill Prevention Equipment Operability Check: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No N | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Intal Service Firms UST Compliance Consultants: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |

Soil and Water Testing Lab:

Other:

No No

| UST Se | ervice P | rovider List (All) - Environmer | ntal Service | e Firms Only | |
|---|-------------|---|--------------|--|------------|
| Company | | Listing Submitte | | Area of state conducts work | |
| INENCO, Inc. | | Phone (704) 662-8192 | | Coastal (East of I-95): Yo | es |
| 132 W. Statesville Avenue | | Fax (704) 662-8194 | | Central (West of I-95 and East of I-77): Yo | |
| Mooresville, NC 27115 | | 1 dx (704) 002-0194 | | | |
| | V | V ebsite | | Mountains (West of I-77): Yo | es |
| Comp | oliance Tes | ting and Monitoring | | UST Equipmment Service Contractor | 'S |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironment | al Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitte | ed 1/5/2022 | Area of state conducts work | |
| Johnson, Spellman & Associates, Inc. | | Phone (770) 447-4555 | | Coastal (East of I-95): Yo | es |
| 350 Research Ct. | | Fax | | Central (West of I-95 and East of I-77): Yo | es |
| Suite 130 Peachtree Corners, GA 30092 | V | Vebsite | | Mountains (West of I-77): Ye | es |
| Comp | oliance Tes | ting and Monitoring | | UST Equipmment Service Contractor | 'S |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | Yes | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: Engineering- Design | Services | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironment | al Service Firms | | Other: Engineering-Desig | n Services |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: Engineering-Design | Services | | |
| | | | | | |

Soil and Water Testing Lab:

| Company | | Listing Submitted | 12/20/2022 | Area of state conducts work | |
|--|---|--|---|--|----------------------------|
| Jones Covey Group | | Phone (888) 972-7581 | | Coastal (East of I-95): Yes | |
| 9595 Lucas Ranch Rd STE 100 | | Fax (909) 484-0300 | | Central (West of I-95 and East of I-77): Yes | |
| Rancho Cucamonga, CA 91730 | | . , | | Mountains (West of I-77): Yes | |
| | W | ebsite | | mountains (West St. 177). | |
| Comp | oliance Testi | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | <u>Yes</u> | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | <u>Yes</u> | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | <u>Yes</u> | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | No |
| Ei | nvironmenta | Il Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 5/27/2020 | Area of state conducts work | |
| Labrador Environmental Consultants, P.C. (ea | stern | Phone (252) 809-9130 | | Coastal (East of I-95): Yes | |
| 1450 Johnson Drive | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Williamston, NC 27892 | | | | Mountains (West of I-77): Yes | |
| | W | ebsite | | | |
| Comp | oliance Testi | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | | | | |
| 0 1 1 10 = 1 | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No No |
| Containment Sump Testing: Corrosion Protection Design Experts: | | | | | |
| | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | No No No No No No No No Trionmenta Yes Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No No No voironmenta Yes Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No No No No No No No Ves | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| UST Service Provider List (All) - Environmental Service Fir | rms Only |
|---|----------|
| | |

| Company | | Listing Submitted | d 8/18/2020 | Area of state conducts work | |
|--|--|--|----------------------------|--|----------------------------|
| Law Petroleum, Inc. | | Phone (704) 573-3535 | | Coastal (East of I-95): Yes | |
| 11025 Arlington Church Road | | Fax (704) 573-3535 | | Central (West of I-95 and East of I-77): Yes | |
| Charlotte, NC 28227 | | (101) 010 000 | | Mountains (West of I-77): Yes | |
| | V | Website | | wouldains (west of 1-77). Tes | |
| Comp | oliance Tes | sting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | <u>Yes</u> | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | <u>Yes</u> | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | <u>Yes</u> |
| Er | nvironment | tal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | d 8/10/2021 | Area of state conducts work | |
| Martin & Slagle GeoSciences, PA | | Phone 8286347741 | | Coastal (East of I-95): No | |
| 173 Sloan Road | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Franklin, NC 28734 | | T dx | | | |
| | V | Website martinandslagle.com | | Mountains (West of I-77): Yes | |
| Comp | | | | | |
| | oliance Tes | eting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | pliance Tes No | | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| _ | | eting and Monitoring | No No | | No No |
| Automatic Line Leak Detector Testing: | No | oting and Monitoring Overfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No To Tronment No Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No Tronment No Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| 05156 | ervice Pr | ovider List (All) - Environment | ai Servic | e Firms Only | |
|---|--------------------------------|---|-----------|--|------------|
| Company | | Listing Submitted | 1/31/2022 | Area of state conducts work | |
| McCallum, P.C. | | Phone (757) 420-9252 | | Coastal (East of I-95): Yes | s |
| 1808 Hayward Avenue | | Fax (757) 424-2874 | | Central (West of I-95 and East of I-77): No | ı |
| Chesapeake, VA 23320 | | | | Mountains (West of I-77): No | |
| | W | ebsite www.mccallumtestinglabs.com | | (********************************* | |
| Comp | pliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | 3 |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Ei | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 4/20/2023 | Area of state conducts work | |
| MGF Environmental, PLLC | | Phone (904) 814-3680 | | Coastal (East of I-95): No | ı |
| 288 Gap Creek Rd | | Fax | | Central (West of I-95 and East of I-77): Yes | S |
| Fletcher, NC 28732 | | | | Mountains (West of I-77): Yes | |
| | W | ebsite mgfenvironmental.com | | mountains (West of 177). 100 | • |
| Comp | pliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | 3 |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| | | | | Other: | |
| E | nvironmenta | I Service Firms | | Other. | |
| Emergency Cleanup - Spill/Release: | <mark>nvironmenta</mark> No | I Service Firms UST Compliance Consultants: | No | Other. | |
| | | | No No | Other. | |

Soil and Water Testing Lab:

Environmental Engineer/Geologist Soil and GW Cleanu Yes

<u>Yes</u>

Waste Disposal and Treatment:

Other:

No

| Company | | Listing Submitted | 9/8/2022 | Area of state conducts work | |
|--|---|---|----------------------------|--|----------------------------|
| Mid-Atlantic Associates, Inc. | | Phone (919) 250-9918 | | Coastal (East of I-95): Yes | |
| 409 Rogers View Ct | | Fax (919) 250-9950 | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27610 | | (313) 230 3300 | | Mountains (West of I-77): Yes | |
| | W | ebsite www.maaonline.com | | Mountains (west of 1-77). Tes | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
| NCPCM | | Phone (919) 782-4411 | | Coastal (East of I-95): Yes | |
| 7300 glenwood ave. | | Fax (919) 782-4414 | | Central (West of I-95 and East of I-77): Yes | |
| raleigh, NC 27612 | | (010) 702 1111 | | | |
| | W | ebsite www.ncpcm.org | | Mountains (West of I-77): Yes | |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | NI- | | | | NIa |
| Containment Comp. Testing | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Containment Sump Testing: Corrosion Protection Design Experts: | | | | | |
| | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No nvironmenta No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No nvironmenta No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: I Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| UST Service Provider List (All) | - Environmenta | I Service | e Firms Only |
|---------------------------------|-------------------|-----------|-----------------------------|
| | Listing Submitted | 7/30/2020 | Area of state conducts work |
| Phone (704) 258-5196 | | | Coastal (East of I-95): |

| Nova Group GBC | | Phone (704) 258-5196 | | | Coastal (East of I-95): Yes | S |
|---|------------|-------------------------------------|-------------------------|------------|--|----|
| 442 South Main St | | Fax | | | Central (West of I-95 and East of I-77): Yes | s |
| Suite # 7 Davidson, NC 28036 | | Website https://www.novagro | upgbc.com/ | | Mountains (West of I-77): Yes | s |
| Comp | oliance Te | sting and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment O | perability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation | n Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testi | ing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integri | ty Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: Environr | mental compliance inspe | ections | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | No |
| Er | nvironmen | ntal Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | | No | | |
| Oil and Solvent Recycling: | No | Other: | due dil | igence | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 11/19/2020 | Area of state conducts work | |
| Paragon Environmental Consultants, Inc. | | Phone (336) 669-6037 | | | Coastal (East of I-95): No | |
| D O Poy 157 | | ` , | | | , | |

| Paragon Environmental Consultants, Inc. | | Phone (336) 669-6037 | | Coastal (East of I-95): No | , |
|---|------------|---|----|--|----|
| P. O. Box 157 Thomasville, NC 27361 | | Fax (336) 476-7708 | | Central (West of I-95 and East of I-77): No | · |
| Thomasville, NC 27501 | Website | | | Mountains (West of I-77): No | |
| Comp | liance T | esting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| En | vironme | ntal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |

Soil and Water Testing Lab:

Company

| Company | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
|---|--------------------------------------|--|--|--|--------------------------|
| Peak Hydrogeologic, PLLC | | Phone (828) 817-5209 | | Coastal (East of I-95): No | |
| 470 Hogback Mountain Road | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Tryon, NC 28782 | | | | Mountains (West of I-77): Yes | |
| | V | Vebsite www.peakhydrogeologic.com | | Wouldains (West of 1-11). Tes | |
| Comp | oliance Test | ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironment | al Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
| Petroleum Equipment and Service, Inc. | | Phone (704) 335-8801 | | Coastal (East of I-95): No | |
| 4125 Sinclair Street | | Fax (704) 342-1672 | | Central (West of I-95 and East of I-77): Yes | |
| PO Box 1949 | | rax (104) 342-1012 | | | |
| Denver, NC 28037 | V | Vebsite <u>www.petroleumequipment.net</u> | | Mountains (West of I-77): Yes | |
| Comp | oliance Test | ting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | Yes | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | | | 100 | | |
| | Yes | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | | | | | <u>Yes</u> <u>Yes</u> |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | |
| | <u>Yes</u> No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No <u>Yes</u> <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | <u>Yes</u> <u>Yes</u> |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes No No No Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes No No No Yes Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes No No No Yes Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes No No No Yes Yes Yes Yes | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No Yes Yes Yes Yes Yes | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Entergency Cleanup - Spill/Release: | Yes No No No Yes Yes Yes No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: | No Yes Yes Yes Yes No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes No No No Yes Yes Yes No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No Yes Yes Yes Yes No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes |

| Company | | Listing Subi | mitted 5/14/2021 | Area of state conducts work | |
|---|--------------------------------|---|------------------|--|--------------|
| Petroleum Solutions Inc. | | Phone (919) 605-1979 | | Coastal (East of I-95): | Yes |
| 3012 Whitehart Ln. | | Fax (919) 773-1704 | | Central (West of I-95 and East of I-77): | |
| 819 Purser Drive | | (313) 773 7704 | | | |
| Raleigh, NC 27606 | W | ebsite <u>www.petroleumsolutionsinc.net</u> | | Mountains (West of I-77): | NO |
| Comp | pliance Testi | ng and Monitoring | | UST Equipmment Service Contracto | ors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check | k: <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments | s): No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Sub | mitted 3/31/2022 | Area of state conducts work | |
| Petroleum Tec | | Phone (980) 781-1000 | | Coastal (East of I-95): | Yes |
| 5420 Powerhouse Ct | | Fax | | Central (West of I-95 and East of I-77): | Yes |
| Concord, NC 28027 | | | | Mountains (West of I-77): | |
| | W | ebsite <u>www.petroleumtec.com</u> | | Wouldains (West of 1-77). | 163 |
| Comp | oliance Testi | ng and Monitoring | | UST Equipmment Service Contractor | ors |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check | k: No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments | s): No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | | Other: | Tank Cleaning | UST Piping/Sump Installation: | No |
| Edak Betedien Worldening Corvices. | No | Outlot: | | | No |
| Line Tightness Testing: | No No | | | UST System Removal: | |
| Line Tightness Testing: | No | I Service Firms | | | ank Cleaning |
| Line Tightness Testing: | No nvironmenta | | No | | |
| Line Tightness Testing: | No nvironmenta | I Service Firms | No No | | |
| Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No nvironmenta Yes No | I Service Firms UST Compliance Consultants: | | | |
| Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No nvironmenta Yes No | UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment: | No | | |

| UST Service Provider List (All) - Environmental Service Firms Only |
|--|
|--|

| Company | | Listing Submit | ted 7/30/2020 | Area of state conducts work | |
|--|--|--|----------------------------|--|---|
| Pilot Geological, PLLC | Pho | ne (336) 310-4527 | | Coastal (East of I-95): Yes | |
| 743 Park Lawn Court | F | ax (336) 310-4527 | | Central (West of I-95 and East of I-77): Yes | |
| PO 128 Kernersville, NC 27285 | | , | | Mountains (West of I-77): Yes | |
| Remersville, INC 27200 | Websi | te <u>www.pilotenviro.com</u> | | | |
| Comp | oliance Testing a | nd Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ove | rfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Stat | istical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spil | Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tan | k Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No UST | Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST | Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Othe | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | rvice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes US1 | Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | Yes US1 | Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes Was | ste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Othe | er: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submit | ted 4/20/2023 | Area of state conducts work | |
| | | | | | |
| Practical Environmental Solutions | Pho | ne (910) 790-8265 | | Coastal (East of I-95): Yes | |
| 5634 Harvest Grove Lane | | ne (910) 790-8265 ax | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| | F | ax | | Central (West of I-95 and East of I-77): Yes | |
| 5634 Harvest Grove Lane | | ax | | | |
| 5634 Harvest Grove Lane Wilmington, NC 28049 | F | te www.oil-tank.com | | Central (West of I-95 and East of I-77): Yes | |
| 5634 Harvest Grove Lane Wilmington, NC 28049 | F Websi Dliance Testing a | te www.oil-tank.com | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No | |
| 5634 Harvest Grove Lane Wilmington, NC 28049 | Websi Dliance Testing a No Ove | te www.oil-tank.com and Monitoring | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors | |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: | Websi Dliance Testing a No Ove No Stat | te www.oil-tank.com Ind Monitoring Iffill Prevention Equipment Operability Check: | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | Websi Dliance Testing a No Ove No Stat No Spil No Tan | te www.oil-tank.com Ind Monitoring rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Websi Dliance Testing a No Ove No Stat No Spil No Tan | te www.oil-tank.com Ind Monitoring rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Websi Dliance Testing a No Ove No Stat No Spil No Tan No UST | te www.oil-tank.com Ind Monitoring rfill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: | No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Websi Dliance Testing a No Ove No Stat No Spil No Tan No UST | te www.oil-tank.com Ind Monitoring Iffill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No Ove No Stat No Spil No Tan No US1 No US1 | te www.oil-tank.com Ind Monitoring Iffill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Websi Dliance Testing at No Ove No State No Spill No Tan No UST No UST No Other | te www.oil-tank.com Ind Monitoring If III Prevention Equipment Operability Check: Institute I ventory Reconciliation Services: Prevention Equipment Testing: It Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Websi Dliance Testing at No Ove No State No Spill No Tan No UST No Other N | te www.oil-tank.com Ind Monitoring If III Prevention Equipment Operability Check: Institute I ventory Reconciliation Services: Prevention Equipment Testing: It Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No Yes |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er | Websi Dliance Testing at No Ove No State No Spill No Tan No UST No Other No Other No Other No UST No Other No UST No Other No UST No Other No UST No UST No Other No UST | te www.oil-tank.com Ind Monitoring Iffill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: k Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: er: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No Yes |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: | Websi Dliance Testing at No Ove No State No Spill No Tan No UST No Other No Other No Other No Other No UST Yes UST Yes UST | te www.oil-tank.com Ind Monitoring Iffill Prevention Equipment Operability Check: istical Iventory Reconciliation Services: Prevention Equipment Testing: It Tightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Compliance Consultants: | No No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No No |
| 5634 Harvest Grove Lane Wilmington, NC 28049 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No Ove No Stat No Spil No Tan No UST No Oth No UST No Oth No Oth No UST | te www.oil-tank.com Ind Monitoring If III Prevention Equipment Operability Check: Institute I ventory Reconciliation Services: Prevention Equipment Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: Internal Linin | No No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No No |

| Company | | Listing Submitted | 10/12/2022 | Area of state conducts work | |
|---|----------------------------------|---|------------|---|------------|
| Practical Environmental Solutions. PC | F | Phone (910) 790-8265 | | Coastal (East of I-95): Yes | |
| 5634 Harvest Grove Ln | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28409 | | T WA | | Mountains (West of I-77): No | |
| | We | bsite <u>www.oil-tank.com</u> | | Wouldains (West of 1-77). No | |
| Comp | oliance Testin | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No (| Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No l | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No l | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No (| Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No l | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | | Other: | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| Company | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
| Precision Tank Service | F | Phone (704) 892-8600 | | Coastal (East of I-95): Yes | |
| 737 Zimmer Road | | Fax (704) 892-8711 | | Central (West of I-95 and East of I-77): Yes | |
| Fort Mill, SC 29707 | | Fax (104) 092-0111 | | | |
| | We | bsite www.precisiontankservice.com | | Mountains (West of I-77): Yes | |
| Comp | oliance Testir | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | | | | UST System Installation - Complete Systems: | No |
| Ecak Detection Equipment Operability Oncok. | <u>Yes</u> | UST Internal Lining Inspections: | No | con cyclem metamation complete cycleme. | |
| Leak Detection Monitoring Services: | | UST Internal Lining Inspections: Other: | No | UST Piping/Sump Installation: | No |
| | | | No | | No No |
| Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes | | No | UST Piping/Sump Installation: | |
| Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes nvironmental | Other: | No Yes | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes nvironmental | Other: Service Firms | | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | Yes Yes nvironmental No No | Other: Service Firms UST Compliance Consultants: | <u>Yes</u> | UST Piping/Sump Installation: UST System Removal: | |
| Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Yes nvironmental No No No No | Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | Yes No | UST Piping/Sump Installation: UST System Removal: | |

| Company | | | Listing Submitted | 1/3/2022 | Area of state conducts work | |
|---|--|--|---|----------------------------------|---|----------------------------------|
| Pyramid Environmental & Engineering, PC | Р | hone (336) 335-3174 | | | Coastal (East of I-95): Yes | |
| 503 Industrial Avenue Greensboro, NC 27406 | | Fax (336) 691-0648 | | | Central (West of I-95 and East of I-77): Yes | |
| 21 100 | We | osite www.PyramidEnvi | onmental.com | | Mountains (West of I-77): Yes | |
| Сотр | oliance Testin | g and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No (| Overfill Prevention Equipment | Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | Statistical Iventory Reconciliat | ion Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipment Te | esting: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | ank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No l | JST Internal Inspections (Inte | grity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No l | JST Internal Lining Inspection | S: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No (| Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | JST Compliance Consultants: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | JST Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes \ | Vaste Disposal and Treatmer | nt: | <u>Yes</u> | | |
| | No. | Other: | | | | |
| Oil and Solvent Recycling: | No (| Allei. | | | | |
| Soil and Water Testing Lab: | Yes | Aller. | | | | |
| | | outer. | Listing Submitted | 4/4/2023 | Area of state conducts work | |
| Soil and Water Testing Lab: | Yes | hone (704) 694-8359 | Listing Submitted | 4/4/2023 | Area of state conducts work Coastal (East of I-95): Yes | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive | Yes | hone (704) 694-8359 | Listing Submitted | 4/4/2023 | Coastal (East of I-95): Yes | |
| Soil and Water Testing Lab: Company Regional Environmental PLLC | Yes | | Listing Submitted | 4/4/2023 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive | Yes | hone (704) 694-8359 | <u> </u> | 4/4/2023 | Coastal (East of I-95): Yes | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 | Yes P | hone (704) 694-8359 Fax | <u> </u> | 4/4/2023 | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 | Yes P We | hone (704) 694-8359 Fax psite www.regionalenv.c | com | 4/4/2023 No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp | Yes P We Dliance Testin | hone (704) 694-8359 Fax psite www.regionalenv.c | Operability Check: | | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors | |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Company Automatic Line Leak Detector Testing: | Yes We Diance Testin No No S | hone (704) 694-8359 Fax psite www.regionalenv.co g and Monitoring Dverfill Prevention Equipment | Operability Check: | No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Company Automatic Line Leak Detector Testing: Containment Sump Testing: | Yes We Diance Testin No No No No No Solution No | hone (704) 694-8359 Fax psite www.regionalenv.c g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat | Operability Check: | No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | Yes We Dliance Testin No (| hone (704) 694-8359 Fax posite www.regionalenv.c g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Te | Operability Check: ion Services: esting: | No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Yes We Diance Testin No (| hone (704) 694-8359 Fax psite www.regionalenv.c g and Monitoring Dverfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Telloriant Tightness Testing: | Operability Check: ion Services: esting: grity Assessments): | No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes We Diance Testin No (| hone (704) 694-8359 Fax posite www.regionalenv.c g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellorian Tightness Testing: UST Internal Inspections (Inte | Operability Check: ion Services: esting: grity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes We Diance Testin No (| hone (704) 694-8359 Fax psite www.regionalenv.c g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellank Tightness Testing: JST Internal Inspections (Intellant) | Operability Check: ion Services: esting: grity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes We Diance Testin No () | hone (704) 694-8359 Fax psite www.regionalenv.c g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellank Tightness Testing: JST Internal Inspections (Intellant) | Operability Check: ion Services: esting: grity Assessments): | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes We Diance Testin No (S) No (S) | hone (704) 694-8359 Fax posite www.regionalenv.co g and Monitoring Dverfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellank Tightness Testing: UST Internal Inspections (Intellection Contents) UST Internal Lining Inspection Other: | Operability Check: ion Services: esting: grity Assessments): s: | No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes We Diance Testin No | hone (704) 694-8359 Fax posite www.regionalenv.co g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellank Tightness Testing: UST Internal Inspections (Intellant) UST Internal Lining Inspection Other: Service Firms | Operability Check: ion Services: esting: grity Assessments): s: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Yes We Diance Testin No | hone (704) 694-8359 Fax Disite www.regionalenv.co g and Monitoring Overfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellank Tightness Testing: UST Internal Inspections (Intellant Internal Lining Inspection Other: Service Firms UST Compliance Consultants: | Operability Check: ion Services: esting: grity Assessments): s: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |
| Company Regional Environmental PLLC 9016 Hazel Forest Drive Fuquay Varina, NC 27526 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes We Diance Testin No () | hone (704) 694-8359 Fax Disite www.regionalenv.co g and Monitoring Diverfill Prevention Equipment Statistical Iventory Reconciliat Spill Prevention Equipment Tellorian Tightness Testing: JST Internal Inspections (Intellors Internal Lining Inspection Other: Service Firms JST Compliance Consultants: JST Equipment Verification: | Operability Check: ion Services: esting: grity Assessments): s: | No No No No No No | Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): No UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No No |

| Company | | Li | sting Submitted | 9/14/2020 | Area of state conducts work | |
|---|--|--|---|----------------------------------|--|----------------------------|
| Schnabel Engineering Sourh, P.C. | Ph | one (910) 769-1621 | | | Coastal (East of I-95): Yes | |
| 244 Princess Street, Suite 205 | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28401 | | | | | Mountains (West of I-77): Yes | |
| | Web | site <u>www.schnabel-eng.com</u> | 1 | | | |
| Comp | oliance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No O | verfill Prevention Equipment Opera | ability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No St | atistical Iventory Reconciliation Se | ervices: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Sp | oill Prevention Equipment Testing: | | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Ta | ank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No US | ST Internal Inspections (Integrity A | Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | ST Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Ot | ther: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental S | ervice Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes US | ST Compliance Consultants: | | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | Yes US | ST Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> W | aste Disposal and Treatment: | | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Ot | ther: | | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | | |
| Company | | Li | sting Submitted | 12/30/2021 | Area of state conducts work | |
| Sensible Solutions Environmental, P. C. | Ph | one (336) 263-0965 | | | Coastal (East of I-95): No | |
| P. O. Box 3074 | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Chapel Hill, NC 27515 | | | | | | |
| | | | | | Mountains (West of I-77): No | |
| | Web | site www.sensible-solutions | -environmental.con | <u>n</u> | Mountains (West of I-77): No | |
| Comp | | site www.sensible-solutions | -environmental.con | <u>n</u> | UST Equipmment Service Contractors | |
| Comp Automatic Line Leak Detector Testing: | oliance Testing | | | n No | . , | No |
| _ | No O | and Monitoring | ability Check: | | UST Equipmment Service Contractors | No No |
| Automatic Line Leak Detector Testing: | No Ot | and Monitoring verfill Prevention Equipment Opera | ability Check: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No Ov No St No Sp | y and Monitoring verfill Prevention Equipment Opera | ability Check: ervices: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No Ov No St No Sp No Ta | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: | ability Check: ervices: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No Or No St No Ta | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: | ability Check: ervices: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No Or No St No Ta No US | yerfill Prevention Equipment Opera catistical Iventory Reconciliation Security Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A | ability Check: ervices: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No Or No St No Ta No US | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A | ability Check: ervices: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Over No St No Ta No US No Over No O | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A ST Internal Lining Inspections: ther: | ability Check: ervices: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Or No St No Ta No US No Or | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A ST Internal Lining Inspections: ther: | ability Check: ervices: assessments): | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Or No St No US No Or | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A ST Internal Lining Inspections: ther: | ability Check: ervices: assessments): | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No Or No St No US No Or | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants: | ability Check: ervices: Assessments): | No No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No Or | y and Monitoring verfill Prevention Equipment Opera catistical Iventory Reconciliation Second Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity A ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants: ST Equipment Verification: | ability Check: ervices: Assessments): | No No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
|--|--------------------------|---|-------------------|------------------|--|------------|
| Singleton Environmental, Inc. | Ph | one (828) 508-4510 | | | Coastal (East of I-95): Yes | |
| PO Box 604 | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Fletcher, NC 28732 | | | | | Mountains (West of I-77): Yes | |
| | Webs | site <u>singletonenvironment</u> | al.com | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ov | erfill Prevention Equipment Op | erability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | atistical Iventory Reconciliation | | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | • | ill Prevention Equipment Testir | ng: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | | nk Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | T Internal Inspections (Integrity | y Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | T Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | | ner: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | No |
| Er | nvironmental S | ervice Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No US | T Compliance Consultants: | | No | | |
| Environmental Engineer/Geologist - Site Checks: | Yes US | T Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> Wa | aste Disposal and Treatment: | | No | | |
| Oil and Solvent Recycling: | No Ot | ner: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 6/29/2021 | Area of state conducts work | |
| SR&R Environmental, Inc. | Ph | one (910) 763-6274 | | | Coastal (East of I-95): Yes | |
| 4920 Highway 421 N. | | Fax (910) 763-6132 | | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28401- | | | | | Mountains (West of I-77): No | |
| | Webs | site <u>www.srrenviro.com</u> | | | | |
| Comp | oliance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | erfill Prevention Equipment Op | | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Sta | atistical Iventory Reconciliation | Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Sp | ill Prevention Equipment Testir | ng: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Ta | nk Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No US | T Internal Inspections (Integrity | y Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | T Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Ot | ner: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| | wironmontal S | ervice Firms | | | Other: | |
| Er | ivironinientai 3 | | | | | |
| Emergency Cleanup - Spill/Release: | | T Compliance Consultants: | | No | | |
| | Yes US | T Compliance Consultants: T Equipment Verification: | | No No | | |
| Emergency Cleanup - Spill/Release: | Yes US | · · | | | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes US No US No Wa | T Equipment Verification: | Vacuum Truck Se | No <u>Yes</u> | | |

| Company | | Listing Submitted | 12/30/2021 | Area of state conducts work | |
|---|---------------------------------------|--|------------|--|--------|
| Terraquest Environmental Consultants, P.C. | P | one (919) 563-9091 | | Coastal (East of I-95): Yes | |
| 100 E. Ruffin Street | | Fax (919) 563-9095 | | Central (West of I-95 and East of I-77): Yes | |
| Mebane, NC 27302 | | (1) | | Mountains (West of I-77): Yes | |
| | Web | site <u>www.terraquestpc.com</u> | | mountains (West of 177). 163 | |
| Comp | oliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | verfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> S | atistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | oill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No U | ST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No U | ST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No C | her: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmental \$ | ervice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | | ST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | | ST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | · | aste Disposal and Treatment: | Yes | | |
| Oil and Solvent Recycling: | · · · · · · · · · · · · · · · · · · · | her: | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | |
| | | Listing Onlywith | 0/40/0000 | Annual state and destance of | |
| Company | | Listing Submitted | 8/12/2020 | Area of state conducts work | |
| TIMMONS GROUP | Pl | one (919) 866-4951 | | Coastal (East of I-95): Yes | |
| 5410 TRINITY ROAD, SUITE 102 RALEIGH, NC 27606 | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| TALLION, NO 27000 | Web | site http://www.timmons.com/ | | Mountains (West of I-77): Yes | |
| Comp | oliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | verfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | atistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | oill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No U | ST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No U | ST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No C | her: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmental \$ | ervice Firms | | Other: SYSTEM DESIGN SERVICES - UST ENGINE | EERING |
| Emergency Cleanup - Spill/Release: | | ST Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | | ST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | aste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | | her: SYSTEM DESIGN SERVICES - UST ENGINE | | | |
| Soil and Water Testing Lab: | | | | | |
| Soil and water resting Lab: | No | | | | |

| Company | | Listing Submitted | d 8/13/2020 | Area of state conducts work | |
|---|--|--|--------------------------------------|--|---------------------------------|
| Unified Services of Texas | | Phone (817) 481-9510 | | Coastal (East of I-95): Yes | |
| 2110 Greenbriar dr. | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Southlake, TX 76092 | | Tux | | | |
| | V | Website <u>ustfuel.com</u> | | Mountains (West of I-77): Yes | |
| Comp | oliance Tes | sting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | <u>Yes</u> | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | <u>Yes</u> | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | <u>Yes</u> |
| Er | nvironment | tal Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Equipment Verification: | Yes | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | <u>Yes</u> | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | d 2/5/2021 | Area of state conducts work | |
| Wildco PES | | Phone (603) 935-9330 | | Coastal (East of I-95): Yes | |
| 440 Harvey Rd | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| 497 Lendall Lane Fredericksburg VA 22405 | | I ax | | | |
| Manchester, NH 3103 | 1 | Website WILDCOPES.COM | | Mountains (West of I-77): No | |
| Comr | | | | | |
| 00 | oliance Tes | sting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | oliance Tes <u>Yes</u> | | Yes | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | Yes |
| _ | | sting and Monitoring | <u>Yes</u> No | | Yes Yes |
| Automatic Line Leak Detector Testing: | Yes | Sting and Monitoring Overfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | <u>Yes</u> <u>Yes</u> No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | <u>Yes</u> <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Yes Yes No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes Yes No No Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No <u>Yes</u> <u>Yes</u> No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes Yes No No Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No No Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No No Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No Yes Yes No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Yes No No Yes Yes Yes Yes Yes Yes | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No Yes Yes No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Yes Yes No No Yes Yes Yes Yes Yes No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: UST Equipment Verification: | No Yes Yes No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Yes No No Yes Yes Yes Yes Yes No No No | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: tal Service Firms UST Compliance Consultants: | No Yes Yes No No Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes Yes Yes Yes |

UST Service Provider List (All) - Environmental Service Firms Only

| Company | | Listing Submitte | d 8/13/2020 | Area of state conducts work | |
|---|------------|--|-------------|--|------------|
| WithersRavenel, Inc. | Phone | 919) 469-3340 | | Coastal (East of I-95): Yes | ; |
| 115 MacKenan Drive Cary, NC 27511 | Fax | C | | Central (West of I-95 and East of I-77): Yes | ; |
| Cary, NO 27511 | Website | www.withersravenel.com | | Mountains (West of I-77): Yes | ; |
| Compliance Testing and Monitoring | | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Overfi | Il Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Statist | ical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spill P | revention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tank 7 | Fightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No UST In | nternal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST In | nternal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Environmental Service Firms | | | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes UST C | Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | Yes UST E | quipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes Waste | Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Other: | Phas | e I ESAs | | |
| Soil and Water Testing Lab: | No | | | | |